

# symbol<sup>®</sup> LS 9208

**Please save this sheet. This sheet is required in the event a scanner needs to be reprogrammed. Before reprogramming a scanner please contact an Edmunds hardware technician.**



USB Interface



**1**



Enable Function Key Mapping

**2**



Scan Options

**3**



<DATA> <SUFFIX>

**4**




Enter

# symbol<sup>®</sup> LS 9208

**Please save this sheet. This sheet is required in the event a scanner needs to be reprogrammed. Before reprogramming a scanner please contact an Edmunds hardware technician.**



Keyboard Wedge Interface



1



IBM PC/AT & IBM PC Compatibles<sup>1</sup>

2



Enable

3



Scan Options

4



<DATA> <SUFFIX>

5



Enter

# symbol<sup>®</sup> LS 9100

**Please save this sheet. This sheet is required in the event a scanner needs to be reprogrammed. Before reprogramming a scanner please contact an Edmunds hardware technician.**



**1**




Set Synapse PC Wedge Defaults

**2**



Enable LS 9100 Communication

**3**




SCAN OPTIONS

**4**




Send Control Key Codes

**5**



<DATA> <SUFFIX>

**6**



ENTER

# symbol<sup>®</sup> LS 9100

**Please save this sheet. This sheet is required in the event a scanner needs to be reprogrammed. Before reprogramming a scanner please contact an Edmunds hardware technician.**




1



Enable Function Key Mapping

2



SCAN OPTIONS

3



<DATA> <SUFFIX>

4



ENTER



1. ENTER/EXIT PROGRAM MODE



2. RECALL DEFAULTS



5. ENTER/EXIT PROGRAM  
MODE

